G. R. S. 59]

GPB—15,000—22-7-14

GENERAL AND REVENUE SECRETARIAT.

1904-05
~~191~~.
(Inward)

File No. 428

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Repairs to Siddu Mallikarjunaswamy on the Hill at Bettadapur, Hunsur Taluk—

PREVIOUS REFERENCES	LATER REFERENCES

OFFICE OF THE DEWAN OF MYSORE

No: 832
Mis: 168-92

Bangalore, 30/8/ 19 ~~189~~

Official Memorandum.

SUBJECT No. 387

Repairs to Sidlu Mallikarjunaswamy temple on the Hill at Bettadapur

Reply of Govt.— An estimate together with a detailed report will be called for from the Deputy Commissioner

THE attention of the Deputy Co of the Mysore District is di to Subject No. 387 of the Dasara Rep sentative Assembly Proceedings of October and he is requested to submit a de report regarding the condition the amount of savings availab at the credit of the Sri S Mallikarjunaswami temple at Bettadapur, Hunsur Taluk, and also an estimate of the probable cost of putting the institution in a state of good repair.

By Order,

27/8/94

Muzrai Secretary.

26/8/94

MUZRAI

1898

From

To The Dy Com^{r}.
Mysore District.

Dated 8th September 98.
Despatched 12—9·98
Received
General No. 357
Muzrai F. No. 168—92
Enclosure No.

Referring to Subject
N^{o}. 429 of the Dasara ~~Rubb~~
~~presentation~~ Proceedings
of October 1897 regarding
the repairs to the Bettadapur
temple, has the honor to
draw the Deputy Com^{r}'s
attention to correspondence
ending with this Office N^{o}. 1269
Muzr F 168-92
dated 10th June 1897, and
to request that the report
called for in regard to the
repairs urgently needed to

to this Office N^{o}. 878 of 22nd
February 1895. And although
more than 3 years have
elapsed since, and a reminder
No
N^{o}. 1269 of 10th June 1897
Muzr F 168-92
was sent to the Dy Com^{r}.,
yet the promised report has
not been received. The Dy Com^{r}.
is now requested to expedite
the submission of the Estimate
for the necessary repairs to
the temple without further
delay.

By order,

Muzr Secy.

the temple may be submitted as early as possible.

2 It is to be observed that the subject of the repairs of the temple in question has been brought up before Govt in successive Dasara Assemblies since 1892. An estimate amounting to Rs 7502 prepared by the Executive Engineer of Mysore was forwarded to the Deputy Comr under cover of this Office No. 715 / Mwxt 168-92 of 13th February 1895, for revision with reference to the urgent and essential requirements of the temple, and thereupon the ~~subje~~ submission of a report on the subject was promised by the Deputy Comr in his Docket

(General Serial No. 30.)

1895

OFFICE OF
481
BRANCH
DEWAN OF MYSORE

17

From

The Deputy Commissioner
Mysore District

To

The ~~Chief~~ Secretary to the Dewan
of Mysore.

Inspr Gl
Refer Gl
28/2/95

Inspr Department

Dated 22nd

Despatched 26th February 195

Received 28/2

Enclosures No.

General No. 878
No.

Award passed
Refer Gl

With reference to his docket no: 715/168, of the 29th Instant, in re the Estimates for repairing Mallikarjuna-Swami temple, on the Bettadapur Hill, has the honor to state that on receipt of the estimate in questions, orders were issued to the Amildar, to inspect the temple, with some of the respectable residents of the place, and to

to suggest what portion of the temple may conveniently pulled down, and what portions retained, with a view to curtail the cost of repairing the temple which is unnecessarily large, and away from roads.

2. Steps will be taken to do the needful, on receipt of a reply from the Amildar.

Deputy Commissioner
Mysore District

Compd
ulu.

(17)

466

29-1

Gen. 30.]

1895

From The Executive Engineer
Mysore Division.

To The Chief Engineer
& Mysore.

Dated Mysore 24th January 1895.

Despatched 26"

Received 29/1

General No. 316

No. 23

Enclosure No.

Have the honour to ask to be examined & estimate & select such of the works as are urgently required & submit the same for sanction & to have it carried out in the ensuing season & to forward the same to this office for record

29/1/95

your Camp No. 222 of 23rd November 1893 forwarding in original Mazarai Secretary's No. 521/168-92 of 18th idem, requesting to prepare an estimate for repairing the Mallikarjuna temple on the Bettadapur hill and to forward the same to the Deputy Commissioner.

In returning the above, has the honor to report that an estimate amounting to Rs. 7,502 for repairing the temple in question has been forwarded

To D.C. Mysore 7/5 8/13/1/95
168.92

Deputy Commissioner on 15th January 1895.

II.— There is nothing of historical or architectural importance about this temple, so it has not been brought on the list of objects of Antiquarian interest in the Mysore Province".—

By Order.
(Signed) V. Rangavelu.
for Executive Engineer
Mysore Division.

Mysore P. W. Department.
Central Office.
Bangalore 29th January 1895

No. 318

Memo:

Copy forwarded to the Secretary to the Dewan of Mysore, Muzarai Department, for information, with reference to his No. 521 dated 18th November 1893

A. V. Subbaiah
Asst to Chief Engineer of Mysore

(18)

Gen. Serial No. 30.]

1894

MUZARAL

From

To The Dy Commrs
Mysore Dist

Dated 13 February 95

Despatched 14

Received

Enclosures No.

General No. 715
Muzarai F. No. 168-92

Has the honor to state that the Chief Engineer of Mysore intimates in his Docket No. 318 of the 29th Ultimo that an estimate amounting to Rs. 7502/ for repairing the Mallikarjunaswami temple on the Bettada-pura Hill, Hunsur Taluk, has been prepared by the Executive Engineer, Mysore Divis

the same no 878 dated 22-2-95

and forwarded to the Dist.t Office, and to observe that the estimated cost of ref is a very large amount.

2. The Dy Commr is therefore reques that out of the items of work provided fo in the estimate prepared by the Exc: Eng. such items of work as are urgently re- quired to be carried out to the temple may be selected and that a revised esti for the same may be submitted to this of for sanction, without making any again on the subject to the aforesaid Exc Engineer.

3. The Dy Commr is also requested to ~~sho~~ out the source from which the cost ~~shou~~ be met.

By or

Ast

Secretary

6.7